


Materials and Processes Engineering's Role in the Reconstruction and Failure Analysis of The Space Shuttle Columbia


Rick Russell

NASA Orbiter Project Support Office


Kennedy Space Center, Florida



STS-107 Timeline




- Launch – January 23, 2003 at 10:39 AM
- Launch + 81.9 seconds, External Tank left bipod foam strikes Columbia's left wing
- February 1, 2003 8:15:30 am, Commander Husband and Pilot McCool execute de-orbit burn
- Entry interface (approx. 400,000 ft), 8:44:09 am
- Over California first signs of debris shedding observed at 8:53:46 am
- Approximately 1 minute 24 seconds into peak heating region of re-entry interface, 8:52:17, an off-nominal temperature in the left main landing gear brake line sensor
- First sign of trouble reported in mission control, at 8:54:24 when four hydraulic sensors were indicating "off-scale low".
- Loss of signal from Columbia recorded at 8:59:32 am.
- Videos made by observers on the ground at 9:00:18 am revealed that the Orbiter was disintegrating



Recovery



- Columbia was traveling at Mach 18 at an altitude of 208,000 feet at time of break-up
- The size of the debris field was 645 miles long and 10 miles wide
- Each piece of debris was photographed, analyzed for potential hazards, given a unique identification
- Each piece's location was noted and a preliminary identification was attempted
- Debris was then sent to one of several stationing locations before being sent to the Kennedy Space Center for reconstruction
- Over 83,900 items were recovered representing an estimated 38% of Columbia by weight




Reconstruction





- Reconstruction is a common aircraft accident investigation tool used to trace damage patterns and failure clues to aid in the determination of probable cause
- A 2-D Reconstruction plan was developed before the arrival of the debris
- The option for possible 3-D reconstruction was deferred until the amount of debris and initial observations were made



Reconstruction Plan





Reconstruction Hanger



Pathfinders




- Six items with similar thermal and mechanical damage to left wing components were selected for failure analysis
- Purpose was to develop failure analysis procedures for debris hardware and to obtain exploratory lab data
- Areas of interest included fracture surfaces, high temperature erosion and melting of fractures and other protrusions, various metal deposits, and various degrees of tile discoloration and deposits.
- The results of the tests and analyses were intended to provide guidance of future failure analyses and provide a basis for debris damage interpretation.






Aluminum Pathfinder




- Intergranular fracture primary failure mode



Early Analysis - Midbody Panel





Early Analysis - Main Landing Gear Uplock Roller





Heaviest splatter on
inboard side



Early Analysis - Landing Gear



Early Analysis - Main Landing Gear – Corner Tile




Early Analysis - Main Landing Gear Tires



Emphasis Placed on Left Hand Wing Leading Edge




- Evidence of extreme overheating and heavy deposits on specific WLE hardware appeared to correlate with the instrumentation and sensor data
- To validate proposed break-up scenarios under consideration the investigation was concentrated on three areas of interest associated with the Wing leading Edge Subsystem (LESS):
 - ◆ Carrier Panel Tiles
 - ◆ RCC Panels
 - ◆ Wing substructure attach hardware



Wing Leading Edge



Reinforced Carbon-Carbon Panels
(1-10 and 16-17)



T-Seals

RCC Panel
Numbers





RH Wing Overview 4-7-03




Torque Box
Xo1191-Xo1365

RH
MLG
Door



Intermediate Wing
Xo1040-Xo1191





LH Wing Overview 4-7-03



3D Reconstruction of Left WLE






Left Wing Tile Table



LESS Observations



- Unique indications of heat damage:
 - ◆ Excessive overheating and slumping of carrier panel tiles
 - ◆ Eroded and knife-edged RCC rib sections
 - ◆ Heavy deposits on select pieces of RCC panels




Left Hand Wing Debris Points to RCC 8/9



(#) = Number of attach fitting bolts on the piece T = Tile piece, no structure
F = Fitting with some RCC in it S = Spar only (metal, no RCC)



Upper C/P	1 14906	2	3 19041	4 51033	5 21066	6 22510	7 50314	8 50336T	9	10	11	Slump
Fitting	1	2	3 853(4)	4 788(4)	5 54043 (4)	6 50950 (4)	7	8	9	10	11 12322 (4)	12
T-Seal	1	2 32171	3	4 24430 49830	5 17974	6 26229	7	8 22467 60875	9	10 63764	11	12 36492 38226
RCC	1 518 16563	2 2023F 52089 34389 1847 47937	3 47918 24736 32044 732	4 L 17969 29288 36519	5 L 54049 57123 57135 36536 37770 55083 26009 36530 36512 29112	6 32055S 59527 61137	7 M 31985 26014 23663	8 H 2200 17957 18477 43709	9 H 7025 27543 29741 49619 52018 61143	10 M 29233 34713 43388	11 L 34664 26027S	12 Slag RCC attach holes intact Erosion
Fitting	1	2 717(2)	3 708(2) 431(2)	4	5 823	6 64805 (3)	7	8	9	10 9413 (2)	11	12
Lower C/P	1 24086	2 24543	3 26022	4 24082 52885T 56168T	5	6 58297	7 1399 27589T	8 38991T 26569T	9 16692T 22571T	10 27563	11 108 24794T 48598T 51645T	Slump



Carrier Panel Tiles




- Per design, lower LESS C/P 9 has 4 OML tiles plus 5 internal tiles
- 4 STS-107 C/P 9 tiles have been positively identified
 - ◆ 3 OML tiles 9 (Positions 1, 3 and 4)
 - ◆ 1 internal tile (Position Unknown)




View looking up




Lower Carrier Panel 9 Tiles




Position 1




Position 3




Position 4



Unknown
Inner




Reconstructed View of LC/P 9 Tile with I/B Tile



Flow Patterns Indicates C/P 9 Was Not Dropped Down Into Flow
Open question: Location of Plasma Flow From Panel 8 to tiles on 9?





Reconstructed View of Lower C/P 9 Tile



Slumping and erosion patterns suggest plasma flow across the carrier panel tile (from 8 toward 10)




Carrier Panel 8 - Upper



Item 50336 (V070-199715-074)

**Slumping and erosion patterns suggest plasma flow
out of leading edge cavity (consistent with vent)**



Left Hand Wing Debris Points to RCC 8/9



(#) = Number of attach fitting bolts on the piece T = Tile piece, no structure
F = Fitting with some RCC in it S = Spar only (metal, no RCC)

Upper C/P	1	2	3	4	5	6	7	8	9	10	11		
	14906		19041	51033	21066	22510	50314	50336T				Slump	
Fitting	1	2	3	4	5	6	7	8	9	10	11	12	
			853(4)	788(4)	54043 (4)	50950 (4)					12322 (4)		
T-Seal	1	2	3	4	5	6	7	8	9	10	11	12	
		32171		24430 49830	17974	26229		22467 60875		63764		36492 38226	
RCC	1	2	3	4	5	6	7	8	9	10	11	12	Slag RCC attach holes intact Erosion
	 518 16563 	 2023F 52089 34389 1847 47937 	 47918 24736 32044 732 	 17969 29288 36519 	 54049 57123 57135 36536 37770 55083 26009 36530 36512 24732 	 32055S 59527 61137 	 31985 26014 23663 	 2200 17957 18477 43709 	 7025 27543 29741 49619 52018 61143 	 29233 34713 43388 	 34664 26027S 	 	
Fitting	1	2	3	4	5	6	7	8	9	10	11	12	
		717(2)	708(2) 431(2)		823	64805 (3)				9413 (2)			
Lower C/P	1	2	3	4	5	6	7	8	9	10	11		Slump
	24086	24543	26022	24082 52885T 56168T		58297	1399 27589T	38991T 26569T	16692T 22571T	27563	108 24794T 48598T 51645T		




Erosion on Panel 8 Upper Inboard Rib




Outboard
apex


49619-003



49619-006




Item 49619



Close-ups of knife edge,
note fibers not visible on
internal surface of panel
due to deposits.


Rib tapers from design
thickness of .365" to .05".



Erosion on Gap Surfaces of Panel 8 Outboard Lug & Matching Heel Piece




24724-047



58291


24724-041



Lug fragment tapers from design thickness of .499", to a Knife Edge with a minimum thickness of 0.063"

External/Outboard surfaces:

- Matching eroded plies between items 24724 and 58291, shows heat flow external to the panel while panel heel and lug were attached
- Slag deposits at lug attach points - evidence that slag deposited after lug no longer attached to fitting
- Inconel bushings missing at holes




Heel fragment tapers from design thickness of .233", to a Knife Edge with a minimum thickness of 0.052"



Erosion on Inside of Panel 8 Outboard Lug & Matching Heel Piece



Fracture match of Items 24724 and 58291,
showing surfaces internal to the panel




Close-up of erosion
on internal surface
of panel lug, note
direction upward
and inwards
towards spar.


Close-up of fracture match, note ply erosion
only on the lug fragment. Evidence suggests
that internal surface of lug was eroded after
heel fractured off.




RCC Panel 8 Erosion Features




Erosion indicates prolonged exposure to plasma heating



Erosion on Panel 9 Upper Inboard Rib




Item 52018




7025 to 52018
interface
shows severe
thermal
erosion –
thickness
ranges from
0.270 to knife
edge of 0.040




Item 7025




7025 internal side shows
presence of slag deposits



RCC Panels 8 & 9 Erosion Features




Erosion indicates prolonged exposure in the panel 8-9 joint area.




Simulated 8-9 Panel Joint




- 3-D Simulation required to help visualize plasma flow damage
 - ♦ To better “read” erosion characteristics
 - ♦ Better understand flow patterns
 - ♦ Help deduce what parts must have been present during re-entry
 - To shadow or protect recovered debris
- Panel 8-9 joint simulation was constructed
 - ♦ Used actual debris from 8-9 joint
 - ♦ Used lower RCC panels 17 & 18 to simulate missing lower 8 & 9 panels



Simulated 8-9 Panel Joint - Lower





Slumping Source for Carrier Panel 9 Tile was Revealed



Slumping and erosion patterns suggest plasma flow across the carrier panel tile (from 8 toward 10)



Slumping of C/P 9 Tile #1 Corresponds with Design Slot in Corner of RCC Panel 8



Evidence of Hot Gas Flow Exiting Design Slot Indicates Significant Breach Was Into Panel 8




RCC Panels 8 & 9 Erosion Features



Erosion indicates prolonged exposure in the panel 8-9 joint area.
Additional effort required to properly "read" the erosion




Erosion indicates prolonged exposure on:
Forward faces of panel 8 aft rib
Forward faces of Panel 9 forward rib



Debris Indicates Highest Probability Initiation Site




- Wing failure initiated in the panel 8 area
 - ♦ Most likely at the panel 8 area near 8-9 joint
 - ♦ Condition existed before or shortly after entry interface



■ RCC
■ Aluminum
■ LI2200
■ LI900


■ Inconel-Dynaflex
■ Inconel 718
■ A-286 steel



Left Hand Wing Debris Points to RCC 8/9



(#) = Number of attach fitting bolts on the piece T = Tile piece, no structure
F = Fitting with some RCC in it S = Spar only (metal, no RCC)




Slag
RCC
attach
holes
intact
Erosion




Relative Metallic Deposition on L/H Wing Materials




*Qualitative deposition assessment:
from "Very Light" to "Very Heavy"*



**Distribution of metallic deposition volume
was centered around panels 8 & 9**



Slag Deposit Example, LH RCC 8



SLAG Deposit on "INSIDE" RCC

High Level Questions



Sample the slag deposits on RCC & Tiles to:


- **Identify the location of breach in the wing leading edge.**
- **Identify the sequence of deposition/events**
- **Understand plasma flow direction and related thermal damage.**



Analysis Plan Challenges



- Understand Pros and Cons of Analysis Techniques (destructive and non-destructive)
 - ♦ Objective is to downselect analysis techniques fast.
- What are the leading edge materials?
- Understand Chemistry of reactions with atmospheric elements.
- Understand effects of melting and mixing of different materials.
- All analysis to be complete by end of May, 2003. Wrap-up in June.



Analysis Techniques



Analysis Technique	Purpose	Why/Advantages
Photography	Photo documentation	Documentation to maintain traceability
Scanning Electron Microscopy – SEM/EDS	Semi-quantitative elemental composition	Elements present, identify difference between top and bottom of sample
X-ray Diffraction - XRD	Identify compounds	Identify compounds of crystalline structure
Electron Microprobe	Identify elements	Determine exact composition
Fourier Transform Infra-Red - FTIR	Qualitative organic composition	If organic, aid in identification
ESCA/XPS	Identify inorganic & organic compounds	Aid in tracking of oxidation states, such as oxide; compound identification
Metallography + SEM	Layering of material	Composition through deposit layers
Inductively coupled plasma - ICP	Quantitative elemental composition	Elements present, Quantify bulk composition of sample
NDE Inspections- Radiography, CT, Ultrasonics	Non-destructive Inspection and identification	See through the material, identify differences in materials, identify defects

Repeatability and Reproducibility of results emphasized




Analysis Approach



- Radiograph RCC panels & Tiles
- Strategically locate samples - minimize the sample count. Two samples of each feature.
- Use diagnostic techniques (X-section, SEM, Microprobe, XRD) to identify:
 - ♦ Content of slag
 - ♦ Layering of slag
- Use “Interpretation Criteria” to correlate deposit analysis <==> WLE source material



Apply results to ALL radiographs and visual features to answer the high level questions.




Radiographic Features




- Four types of deposit patterns were identified from LH RCC Panel 8:
 - ♦ Uniformly thick; Spheroidal; Tear-shaped; Globular




Radiography WLE LH Panel 8




X-ray Image



Hardware



LH RCC 8 Upper Apex




Interpretation Criteria - Examples




- How to identify specific alloys in the deposit?
 - ♦ A286 or IN601, IN718, IN625 can be distinguished based on (Ni/Fe) ratio and evidence and amounts of Mo, Nb, Co and Ti.
 - ♦ 2024 can be identified by presence of metallic Al + Cu, Al_2O_3 + Cu.
- How to identify Cerachrome in deposit?
 - ♦ Cerachrome is approximately 43% Al_2O_3 53% SiO_2 3% Cr_2O_3 .
 - ♦ It can be identified from a combination of back-scattered imaging, color, x-ray diffraction and presence and quantification of Al, Si, O, & Cr.
- How to identify SiO_2 from Tile?
 - ♦ SiO_2 from tile will not have with other elements as in cerachrome. It could still pick up a coating of alumina then morphological features will be used to distinguish.





LH RCC 8 – Slag Feature: Thick Tear Shaped




Slag Item 43709, Sample 2A1




Radiograph of Item 43709




LH RCC 8 – Slag Feature: Thick Globules



Slag Item 2200, Sample 6A1




Radiograph of Item 2200




USA
United Space Alliance

BOEING


LH RCC 8 – Slag Feature: Spheroids



Slag Item 2200, Sample 6C1




Radiograph of Slag Item 2200



USA
United Space Alliance

BOEING

LH RCC 8 – Slag Feature: Uniform Deposit




Slag Item 16523, Sample 4A1


Cerachrome+Aluminum+Inconel+Alumina

Aluminum+Inconel+Cerachrome+Type A Coating

SiC



Radiograph of Item 16523




Significant Findings - Sampling LH RCC Panel 8



- ♦ Large amounts of melted ceramic cerachrome insulator
 - High temperature $>3200^{\circ}\text{F}$
- ♦ No indication of stainless steel spar fittings (A286) in slag
 - Breach location away from spar fittings
- ♦ Cerachrome + Inconel in first deposited layers
 - Melting of spanner/foil/fittings + Insulator
- ♦ Aluminum deposition secondary event

Slag layering suggests plasma impingement location


Slag distribution & shape suggests plasma flow direction and deposition duration



Significant Findings – Sampling All Other Panels




- Significant findings includes all LH RCC Panels except panel 8 and all RH RCC panels sampled
- All analyzed slag layers contain aluminum
 - ♦ CONCURRENT Spar/Inconel/Insulator melting
- Slag is generally uniform and relatively thin
 - ♦ No region where melting was concentrated
 - i.e. plasma heating for short periods



LH RCC Panel 9 Lower CP Tiles



Horse Collar Fabric Deposit



57754

22571

50338

16692

Molten Slag on Tile

Insert

Tile Slumping



C
P
8

Realtime X-ray, Sidewall View


Spar
↑
↓
RCC

Carrier Panel

High-Z material




(IML)




These findings suggest flow of material from inside the RCC out through the upper and lower CP locations.

Proposed Breach Location and Plasma Flow




Flow Exiting through RCC 8 on to lower Carrier Panel 9 tiles



Additional Corroborating Information - RCC Panel Debris Locations



- Left Wing RCC
- Left Wing Eroded RCC
- Right Wing RCC



- Panels at RCC 8 and Aft Dropped First
- All Eroded RCC Pieces (in 8 & 9) Found to the West
- R/H Wing Panels and L/H Wing Panels 1-8 Found to the East




Additional Corroborating Information - Image Analysis



Trajectory analysis from JSC Image Analysis:

- Trajectory “pipe” of one foot diameter mapped onto the left wing
- Centerline of pipe intersects the wing at approximately RCC panel 8, with most likely foam impact predicted along panels 7 and 8.




Impact Near T-Seal to RCC 8-9 Carrier Panel Joint is a Possibility



Overall Forensic Conclusions



- Overall forensic assessment is consistent with M&P Team conclusions
- All forensic evidence suggests a breach occurred on the lower surface of the LH RCC panel 8, close to the T-seal with panel 9
- The breach was present early during reentry allowing the ingestion of hot gasses into the wing leading edge cavity, which continued for several minutes prior to vehicle breakup
- Sequence of events:
 - ◆ Melting and vaporizing the Inconel 601 foil-covered cerachrome insulation blankets
 - ◆ Slumping the wing carrier panel tile immediately aft of the breach
 - ◆ Eroding the RCC adjacent to, and downstream of, the breach
 - ◆ Melting and/or weakening the Inconel 718 and A286 leading edge attach hardware
 - ◆ Destroying the nearby instrumentation and wire bundles
 - ◆ Penetrating the aluminum wing leading edge spar



Conclusions



- The hot gasses, having flooded the wing interior, quickly heated the upper and lower wing surfaces allowing the aluminum honeycomb facesheets and the wing tiles to debond. The thin-wall aluminum truss tubes would soon collapse and the aerodynamic and structural integrity of the left wing would be effectively destroyed
- The forensic evidence is consistent with the observed External Tank foam impact 81 seconds into launch. This is the most probable cause of the damage to the RCC leading edge.

